

RFP NUMBER HOAC HO 48060

Bidder's Enquiry:

- Can you please confirm the correct description and drawing number for item6.  
Under the BOQ,the description is as follows : Single Phase Relay Testing Device  
Under pages1-5 of the Specification No BBH7415,the description is as follows:  
THREE-PHASE TRANSFORMER TURNS RATIO TESTER  
Under TENDER EVALUATION METHODOLOGY ,the description is as follows: SINGLE  
PHASE RELAY TESTING DEVICE ,Drawing No: BBH7418

Response:

- Please note as per the RFP item 6 is the SINGLE PHASE RELAY TESTING DEVICE,  
Drawing No: BBH7418, the current RFP does not cover the scope of Three phase  
transformer turns ratio tester and specification BBH7415.

Bidder's Enquiry:

- We have realized that the specification for Single phase Relay Testing Device is  
not included in the Annexure B spec, can you please send it to us

Response:

- Checked and it is true that spec is missing in the pack, kindly find attached as -  
BBH7418