

Document Title	:
	Repairs to service gate & motor at EES workshop
Project Title:	
To carry or	ut repairs to service gate at EES workshop.
	REVISION 01: FOR QUOTATION

1. Authorization Signature

Requested by: Approved by:

Amar Hurku Mandlenkosi Vilakazi

Technical Supervisor (Pier 1) Act Technical Manager

Date: 05 May 2025 2025 Date 05/05/2025

1. SCOPE BACKGROUND

Durban Container Terminal Pier 1 uses service gate to give access to heavy machinery / equipment to the

workshop.

2. SCOPE OF WORKS

NOTE: the approved contractor shall preform the job according to the provided scope of work. Any

deviations from the scope of work must be discussed and approved by the project leader before work can

commence. Any work done by the contractor is subject to the inspection by Transnet and incompetent

practice shall be disapproved.

2.1 System Functions

The object of this scope of work is for contractor to repair service gate & motor. The outcome of this

project is to achieve the following:

To ensure reliability

To eliminate unforeseen breakdowns

• Equipment safe for use

2.2 **WORK TO BE CONDUCTED**

Make: Centurion

To replace sliding gate wheels

To replace guide rollers

To replace damaged rack and realign

To Replace gate motor with D20

3. SAFETY

It is the responsibility of the contractor to ensure that the team working on site conduct work in a safe

manner. To abide by the safety standards of Transnet.

3

4. INCLUSION

Transnet Port terminal will provide the following:

• Access permit to the site

5. EXCLUSIONS:

Transnet Port Terminal will not provide the following:

- Labour shall be at the contractor's expense
- Forklift certified operator
- All costs, including transportation, shall be at the contractor' expense
- Hot work permits

6. EVALUATION CRITERIA

Please refer to the evaluation criteria. It is the responsibility of the bidder to go through the evaluation criteria and submit all relevant documentation. Please note that if a bidder does not meet the minimum eligibility criteria, the bid will be disqualified.