ANNEXURE B: HEAVY CLEANING OF THE PHELOPEHA HEALTHCARE TRAINS									
TECHNICAL ELEMENT	REQUIREMENT	RESPONSE		WEIGHTING	RATING MATRIX	EVIDENCE / COMMENTS / COMPLIANCE	RESPONDENT COMMENTS		
	Compliance to technical	YES	NO		Compliance - 60	Signed off documentation: Annexure A			
	Compliance to technical specification			60	Compliance = 60 Non-compliance = 0				
LEAD TIME	Indicate duration to render service	Indicate duration (weeks)			1 weeks or less = $40$ 2 weeks = $20$ More than 3 weeks = $0$				
					Hore than 5 weeks = 0				
Weighted score	100								
Threshold	80								

SUBMITTED

Signature:\_\_\_\_\_

Date: 05/11/2024

Name: <u>Wade Arendsen</u> Designation:

Designation: Engineering Technician

Annexure A: Technical Specifications for Heavy Cleaning							
Item No.	Item Description	Comply (Yes) / Not Comply (No)					
NSI	Perform heavy cleaning and degreasing on the extraction canopies Scope: 1) Remove the filter and perform a heavy clean 2) Remove non-fixed parts of the extraction canopies and perform a heavy clean and polish 3) Issue a certificate by an accredited company (per coach) Coaches: 1) Coach 4: Kitchen - Coach number: 135162 (Phelophepa 1) 2) Coach 5: Diner - Coach number: 134090 (Phelophepa 2) 3) Diner - Coach number: D125721 (Transvaco)						
NSI	Perform train interior and exterior heavy cleaning Scope: 1) Heavy/deep clean and polish all floors and interior panels and surfaces (done after the train maintenance is complete) 2) Heavy/deep clean all coach windows, interior and exterior 3) Heavy/deep clean the coach body exterior (done after the train maintenance is complete) Coaches: Phelophepa 1: All coaches Phelophepa 2: All coaches						

SUBMITTED

Name: Wade Arendsen Designation: Engineering Technician

Signature: Micendan

Date: \_\_\_\_\_05/11/2024